


dcmc_sep_exc_8.sqproj



Note: $b_{\text{damp}}=0 \rightarrow$ unstable after torque reversal.
Make it non-zero.